

Effective November 15, 2018 Northern Border is issuing an OFO watch for the following receipt point that is delivering gas that does not conform to the gas quality standards specified in Northern Border Tariff Section 6.5 - paragraph 1(c):

Hay Butte Receipt
DRN# 1367615

The issuance is per Northern Border Tariff Section 6.10.6 - Interruption of Service.

The OFO watch is now in effect and the interconnecting party has until 5:00 p.m. November 15, 2018 to remediate this issue. If the issue is not remediated within this timeframe Northern Border will, pursuant to Northern Border Tariff Section 5.6 Quality of Gas, issue an OFO requiring immediate shut-in of gas supply into Northern Border at such interconnect.

Please contact your Northern Border Nominations Representative at (888) 750-6275 with any questions regarding nominations or scheduling.

Please contact Jim Witte, Gas Quality Lead, at (832) 320-6745 for any gas quality questions.

Please contact Paul Oliver, Manager of Gas Control at (832)-320-5885 with any questions regarding pipeline operations.